	A	В	С	D	E	F	G
1	## North America Emission Control Area Fuel Oil Non-Availability Report						
2	## ECA0100						
3	## 1	2	3	4	5	6	7
4	ECA0100	Ultrabulk	M/V JUPITER CHARM	Panama	9557238	1/28/2013	Panjang, Indonesia
5	##(Include Double Pound for comments, not form fields)						
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice

	Н	1	J	К
1				
2				
3	8	9	10	11
4	Bell Bay, Australia + Gladstone, Austraila + Townsville, Australlia	Honolulu, HI	NA	NA
5				
6	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption

	L	M	N	0	Р	Q
1						
2						
3	12	13	14	15	16	17
4	NA	4/1/2014	12:00	3.5	10	Seattle, WA
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC

	R	S	Т	U	V
1	1				
2	2				
3	18	19	20	21	22
4	4 Yes	Yes	NA	NA	NA
5	5				
E	6 Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?

	w	X	Υ	Z
1				
2				
3	23	24	25	26
4	NA	NA	4/4/2014	12:00
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?

	AA	AB	AC	AD	AE
1					
2					
3	27	28	29	30	31
4	No	NA	NA	Yes	6
5					
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports

	AF	AG	АН
1			
2			
3	32	33	34
4	Mr. Mark Hanna	mark.hanna@ultrabulk.com	203 964 2121
5			
6	Designated Corporate Official Name	Designated Corporate Official E-mail	Designated Corporate Official Phone Number

	Al	
1		
2		
3		35
4	On this case the supplier who supplied LSIFO in Singapore short loaded 25MT. Had there Not been a short loading we would have been compliant with NAECA zone.	
5		
6	Description of Actions to Achieve Compliance	